


Programming Interface

Screw Terminals

Start




- R7 8.2K
- R8 8.2K
- R9 8.2K
- R10 8.2K
- R11 8.2K
- R12 8.2K

- R1 8.2K
- R2 8.2K
- R3 8.2K
- R4 8.2K
- R5 8.2K
- R6 8.2K

C3
0.01uF

D13



Isolation required to allow switches to be wired to multiple controllers in parallel.

Note: Pins 4 and 5 of the programming interface can be used as switch or analog inputs for future applications

General Purpose Controller - V3

Revised 6/15/09